


## **COMBUSTIBLE DUST ROADMAP**


This chart illustrates a typical process for a process owner if combustible dust may be produced or handled in a process. The process owner's final selection of dust collectors and risk mitigation strategies should be based on the outcome of a Dust Hazard / Process Hazard Analysis performed by the process owner. Although early engagement of a dust collector supplier provides helpful insights on the availability and features of various products, process owners should consult with a combustible dust expert and/or a process safety expert before making actual product and mitigation strategy selections.





Important Information: It is the process owner's responsibility to understand the risks in their process and to mitigate those risks in accordance with all applicable laws, regulations and standards, including consideration of those published by the NFPA. Note this Roadmap may not identify all potential mitigation steps and does not cover the commissioning and on-going testing and maintenance required for various mitigation strategies. This roadmap is a high-level summary of steps for a process owner to consider and is not intended as a replacement for careful review of all applicable laws, regulations, and standards. Equipment suppliers can assist a process owner in understanding what products are available to help mitigate their risks but they are not regulatory experts. If you need assistance finding an expert in the field, please contact us and we will assist you in finding resource options. Please note that various strategies can help mitigate, but not eliminate the risks of fire and explosion.

## **EXAMPLES OF MITIGATION SELECTIONS**

The results below reflect common situations, however mitigation strategies are influenced by variables not included in this simplified chart. Process owners should use the outcome of their PHA and discussions with mitigation strategy experts before making actual strategy selections.







©2016 Donaldson Company, Inc.

Please See Important Information on Page 1

donaldsontorit.com • Tel 800-365-1331 (USA) • Tel 800-343-3639 (within Mexico)